

Sharon Mills County Park
Sharon Township, Washtenaw County, Michigan
Photographs 2013 taken by: Stantec and 2015 taken by: Mannik Smith Group



August 27, 2013
Downstream left embankment with grouted rip rap armoring



April 27, 2015
Downstream left embankment with grouted rip rap armoring



August 27, 2013
Damage to grouted rip rap



April 27, 2015
Damage to grouted rip rap



August 27, 2013
Shore erosion above rip rap



April 27, 2015
Shore erosion above the grouted rip rap

Sharon Mills County Park
Sharon Township, Washtenaw County, Michigan
Photographs 2013 taken by: Stantec and 2015 taken by: Mannik Smith Group



August 27, 2013
Shore erosion adjacent to abutment



April 27, 2015
Shore erosion adjacent to abutment.